
Smoke and Dye Testing Summary

High Level Sewershed

Run Summary —							
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-117	Smoke	10/17/2008	ADS/TM	S09OO_014MH	Dry	Yes	2,222.86



Smoke and Dye Testing Summary

High Level Sewershed

Run Summar	y 						
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-117	Smoke	10/17/2008	ADS/TM	S09OO_014MH	Dry	Yes	2,222.86

Isolated Pipes

\$0900_033G1 \$0900_033MH \$0900_022MH \$15.8516 \$0900_006G1 \$0900_006MH \$0900_012MH \$197.3399 \$0900_009G1 \$0900_009MH \$0900_033MH \$39.98783 \$0900_041G1 \$0900_041DE \$0900_014MH \$139.1407 \$0900_003G1 \$0900_003MH \$0900_012MH \$147.3637 \$0900_022G1 \$0900_022MH \$0900_014MH \$229.1048 \$0900_021G1 \$0900_021MH \$0900_006MH \$64.72999 \$0900_005G1 \$0900_005MH \$0900_023MH \$208.8591	neter n)
S0900_006G1 S0900_006MH S0900_012MH 197.3399 S0900_009G1 S0900_009MH S0900_033MH 39.98783 S0900_041G1 S0900_041DE S0900_014MH 139.1407 S0900_003G1 S0900_003MH S0900_012MH 147.3637 S0900_022G1 S0900_022MH S0900_014MH 229.1048 S0900_021G1 S0900_021MH S0900_006MH 64.72999 S0900_005G1 S0900_005MH S0900_023MH 208.8591	8
\$0900_009G1 \$0900_009MH \$0900_033MH \$9.98783 \$0900_041G1 \$0900_041DE \$0900_014MH \$139.1407 \$0900_003G1 \$0900_003MH \$0900_012MH \$147.3637 \$0900_022G1 \$0900_022MH \$0900_014MH \$229.1048 \$0900_021G1 \$0900_021MH \$0900_006MH \$64.72999 \$0900_005G1 \$0900_005MH \$0900_023MH \$208.8591	8
S0900_041G1 S0900_041DE S0900_014MH 139.1407 S0900_003G1 S0900_003MH S0900_012MH 147.3637 S0900_022G1 S0900_022MH S0900_014MH 229.1048 S0900_021G1 S0900_021MH S0900_006MH 64.72999 S0900_005G1 S0900_005MH S0900_023MH 208.8591	8
S09OO_003G1 S09OO_003MH S09OO_012MH 147.3637 S09OO_022G1 S09OO_022MH S09OO_014MH 229.1048 S09OO_021G1 S09OO_021MH S09OO_006MH 64.72999 S09OO_005G1 S09OO_005MH S09OO_023MH 208.8591	8
S09OO_022G1 S09OO_022MH S09OO_014MH 229.1048 S09OO_021G1 S09OO_021MH S09OO_006MH 64.72999 S09OO_005G1 S09OO_005MH S09OO_023MH 208.8591	8
S09OO_021G1 S09OO_021MH S09OO_006MH 64.72999 S09OO_005G1 S09OO_005MH S09OO_023MH 208.8591	8
S09OO_005G1	8
	8
S1100 011G1 S1100 011MH S11MM 043MH 288 3493	8
2.1.00_0.1.01	8
S09OO_023G1	8
S0900_014G1 S0900_014MH S1100_016MH 143.4873	8
S1100_016G1 S1100_016MH S1100_011MH 47.85394	8

Observations & Photos

Obs_ID S1028-117-OB01 **Address** 2522 Ellamont St

Status Private
Source Cleanout
Location Yard - back

Nearest MH S0900_012MH

Comments Smoke from cleanout in back yard. 2522



Picture \S1028-117-OB01-P01.jpg

Comments Back of house, 2522 Ellamont St.

Obs_ID S1028-117-OB02 **Address** 3215 Piedmont Ave

Status Private
Source Cleanout

Location Yard - back **Nearest MH** S09OO_006MH

Comments Smoke from cleanout in back yard. 3215

Piedmont Ave.



Picture \S1028-117-OB02-P01.jpg

Comments Back of house, 3215 Piedmont

Ave.



Wednesday, March 25, 2009

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary Date Ground Total Notification Company / **Test ID** Length **Test Type Inspected Blower MH** Condition Made? Super. S1028-117 10/17/2008 S09OO_014MH Yes Smoke ADS/TM Dry 2,222.86

Obs_ID S1028-117-OB03 **Address** 3200 Mondawmin Ave

Status Private Source Other Other Location

Nearest MH S0900_014MH

Smoke from pvc pipe in side of house along Comments

alley. 8 ft. from ground. 3200 Mondawmin Ave.



Picture \S1028-117-OB03-P01.jpg

Comments Side of house, 3200 Mondawmin

Ave.